

Quick Tips

- **Changing a bad Feature** that has been dimensioned out to a new identical feature that is good. Just rename the old Feature to something that is not used. Exam (LN_3 to LN_3old). Then rename the newly constructed Feature to the original name (LN_3). Now change the Dimension to look for LN_3 not LN_3old. Finally you can now delete the old line Feature without anything lost.
- **Constructing Lines** by using 3D line whenever possible. This way you never have to worry about being in the right work plan. This will save you a few steps in your programming.